
CONJUNTO APOYA PIES CONDUCTOR



Rating: Not Rated Yet

Price:

Variant price modifier:

Base price with tax:

Price with discount:

Salesprice with discount:

Sales price:

Sales price without tax:

Discount:

Tax amount:

Ask a question about this product

Description

	Ref.	Título		Código
1		PEDALIN APOYA PIE CONDUCTOR ARMADO	50-42300	
2		BARRA APOYA PIES CONDUCTOR	50-42310	
3		PATINES DE GOMA CONDUCTOR	50-42381	
4		SOSTÉN LATERAL	50-42210	
5		BULON I CON CABEZA	50-93121	
6		TUERCA M10X1.25	50-GB/T6-13	
7		RESORTE SOSTÉN LATERAL	50-42922	
8		BULON M8X16	50-GB/T1-9	
9		GUÍA PATINES DE GOMA	50-42315	
10		BULON INTERIOR PATINES	50-93351	

1 / 2